## FORM R-1

[seeRegulation 3(4)]

## CERTIFICATE BY ARCHITECT

(To be uploaded by the Promoter on his webpage on the RERA website before withdrawal of money from separate account)

To.

10,	
The SAMANVAY BUILDMART PRIVATE LIMITED, FLAT NOT-01, 3 P NO. 189, MOTI NAGAR, QUEENS ROAD, VAISHALI NAGAR, Jaip Rajasthan, 302021.  Subject: Certificate of percentage of completion of construction work of THE N DOOR of the Phase of the Project (RERA Registration Number is RAJ/P/2020/1 situated KHASRA NO 153,160,161/2, CHATARPURA URF LALYA KAB Jaipur - 302026 (Rajasthan). on the demarcated by its boundaries (latitude longitude of the end points) to the North to the South to the West vil KHASRA NO 153,160,161/2, CHATARPURA URF LALYA KABAS, Jaip	EW 276 AS, and the lage-
302026 (Rajasthan) District JAIPUR PIN 302023 admeasuring 7891.67 sq.m. Area being developed by. SAMANVAY BUILDMART PRIVATE LIMITED	ts.
Sir,	
Shri krishan have undertaken assignment as Architect of certifyingpercentage completion of construction work of the above Building(s) of the Phase of Project, situated on the KHASRA NO 153,160,161/2, CHATARPURA LALYA KABAS, Jaipur - 302026 (Rajasthan). admeasuring 7891.67 sq.mts. being developed by SAMANVAY BUILDMART PRIVATE LIMITED.	the URF Area
1. Based on site inspection, with respect to each of the Building of the afores	
RealEstate Project, I certify that as on the date, the percentage of work do	
foreach of the building of the Real Estate Project (registration number	
RAJ/P/2020/1276 under Rajasthan RERA), is as per TABLE-A herein below.	The
percentage of the work executed with respect to each of the activity of the en	ntire
phase is detailed in TABLE-B.TABLE-A	

Building Number A,B,C,D(to be prepared separately for each Building of the Project)

Time period 01st Jan 2021 to 31st March 2021

SHRI KRISHAN ARCHITECT CA/99/25451

Sr.	Tasks /Activity	Percentage of work	Block B	Block C	Block D
No.		done(Approximately)			
		Block A			
1	Excavation	nil	100%	100%	100%
2	number of Basement(s) and Plinth	nil	nil	nil	Nil
3	Stilt Floor	nil	nil	80%	80%
4	number of Slabs of Super Structure	nil	nil	8	8
5	Internal Walls, Internal Plaster,	nil	nil	36%	36%
	Floorings within Flats/Premises,		7-7-1		
o frie	Doors and Windows to each of the		NO.	LUL LAND	La Charles Barrier
	Flat/ Premises.		HE TO STATE	CPP STATE	ti sistem fork
6	Sanitary Fittings within the	nil	nil	20%	20%
	Flat/Premises,				
	Electrical within the Flat/Premises				
	Fittings	.,	nil	9	9
7	Staircases, Lifts Wells and Lobbies	nil	nii	,	
	at each Floor level connecting				
	Staircases and Lifts, Overhead and	-			
1	Underground Water Tanks.e. •		nil	nil	nil
1	The external plumbing and external	nil	1111	1111	
- 1	plaster, elevation, completion of				
	terraces with waterproofing of the				- 1-7
	Building/ Wing	nil	nil	nil	nil
9	Installation of lifts, water pumps,	mi Mariana di Mariana Mariana di Mariana Mariana di Mariana Ma Mariana Ma Ma Ma Mariana Mariana Ma Ma Ma Ma Ma Ma Ma Ma Ma Ma Ma Ma Ma			al.
	Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings				
	A mana electro				
, ,	mechanical equipment, Compliance				
	to conditions of environment /CRZ				
	NOC, Finishing to entrance lobby/s,				
	plinth protection, paving of areas				
	appurtenant to Building, Compound				
	Wall and all other requirements as				
	may be required to obtain				
	Completion Certificate.		(		-

SHRI KRISHAN ARCHITECT CA/99/25451

TABLE-B

Internal and External Development Works in respect of the entire Registered Phase/Project.

Sr.No	Common areas and Facilities/Amenities	Proposed (Yes/No)	Percentage of Work done		ě.	
(1)		(3)	Block A	Block b	Block c	Block d
1	Internal Roads & Footpaths.		NILL	NILL	NILL	NILL
2	Water Supply		NILL	NILL	NILL	NILL
3	Sewerage (chamber, lines,		NILL	NILL	NILL	NILL
4	Storm Water Drains		NILL	NILL	NILL	NILL
5	Landscaping& Tree Planting.		30%	30%	30%	30%
6	Street Lighting		NILL	NILL	NILL	NILL
7	Community Buildings		NILL	NILL	NILL	NILL
8	Treatment and disposal of		NILL	NILL	NILL	NILL
9	Solid Waste management &		NILL	NILL	NILL	NILL
10	Water conservation, Rain		NILL	NILL	NILL	NILL
11	Energy management		NILL	NILL	NILL	NILL
12	Fire protection and fire safety		NILL	NILL	NILL	NILL
13	Electrical meter room, substation, receiving station.		NILL	NILL	NILL	NILL
14	RAFT COPLITED OF		NILL	100%	100%	
15	COLUMN WITH		NILL	NILL	80%	80%
		4-1,4				
16	BOUNDARY WALL	CAN STREET	90%	90%	90%	90%
17	SITE	经数据证据	100%	100%	100%	100%
18	EARTH BACK FILLING	Mary Car	NILL	100%	100%	100%
19	LABOUR QUARTERS		100%	100%	100%	100%
20	STORE & GOWDON		100%	100%	100%	100%
21	SAMPLE FLAT		100%	100%	100%	100%

Yours Faitafully,
HRI KRISHAN
ARCHITECT
CA/99/25451
Signature & Name
SHRI KRISHAN

C-49, VIDYA APPARTMENT, BAPU NAGAR, JAIPUR

Place: JAIPUR. Date: 07-04-2021