Navik Architects

ARCHITECTURE I INTERIORS I LANDSCAPING I CONSULTANTS

FORM R-1

[See Regulation 3(4)] CERTIFICATE BY ARCHITECT

To, Mr. Lokesh Yadav Authorized Signatory Gokul Kripa Colonizers and Developers Pvt. Ltd. 702-703, Okay Plus Square, Sector-7, Madhyam Marg, Mansarovar, Jaipur, Rajasthan - 302020, Subject: Certificate of percentage of completion of construction work of "Royal Homes" Residential Group Housing scheme of the project (RERA Registration Number (RAJ/P/2021/1469) situated on the Khasra No. 96/1, 95/2 S.N. 111 demarcated by its to the North boundaries (latitude and longitude of the end points)

to the East

developed by Gokul Kripa Colonizers and Developers Pvt. Ltd.

Sir,

South

I VIKRAM JANGID have undertaken assignment as Architect of certifying percentage of completion of construction work of the "Royal Homes" building(s) of the Project, situated on the KhasraNo./PlotNo-96/1, 95/2 S.N. 111 village- Govindpura Urf Jaichandpura Tehsil and District - Jaipur, PIN 302025 admeasuring 8345.70 sq. mts. Area being developed by Gokul Kripa Colonizers and Developers Pvt. Ltd.

Tehsil and District - Jaipur, PIN 302025 admeasuring 8345.70 sq. mts. Area being

to the West Village- Govindpura Urf Jaichandpura

Based on site Inspection, with respect to each of the building(s) of the aforesaid Real Estate Project, I certified that as on the date 30/04/2022, the percentage of work done for each of the building of the Real Estate Project (Registration number RAJ/P/2021/1469 under Rajasthan RERA), is as per TABLE-A herein below. The percentage of the work executed with respect to each of the activity of the entire phase is detailed in TABLE-B.

Ar Vikram Jangid CA/2019/112029

Navik Architects

ARCHITECTURE I INTERIORS I LANDSCAPING I CONSULTANTS

TABLE A Building: - Royal Homes

(To be prepared separately for each Building of the Project)

| S.No. | Task/Activity | Percentage of work done(Approximately) | |
|-------|---|--|--|
| (1) | (2) | (3) | |
| 1 | Excavation | 80% | |
| 2 | number of Basement(s) and Plinth | N/A | |
| 3 | Stilt Floor | N/A | |
| 4 | 45 number of Slabs of Super Structure | 80% | |
| 5 | Internal Walls, Internal Plaster, Floorings within Flats/ Premises, Doors and Windows to each of the Flat/Premises. | 80% | |
| 6 | Sanitary Fittings within the Flat/ Premises, Electrical Fittings within the Flat/ Premises. | 70% | |
| 7 | Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts-(N.A.) Overhead and Underground Water Tanks. | 60% | |
| 8 | The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/wing. | 70% | |
| 9 | Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, Compliance to conditions of environment/ CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building, Compound Wall and all other requirements as may be required to obtain Completion Certificate. | N/A | |

Ar Vikram Jangid CA / 2019/112029

Navik Architects

ARCHITECTURE I INTERIORS I LANDSCAPING I CONSULTANTS

TABLE-B
Internal and External Development Works in respect of the entire Registered Phase/Project.

| S.No. | Common areas and Facilities/Amenities | Proposed (Yes/No) | Percentage of work done | Details |
|-------|---|-------------------|-------------------------|---------|
| (1) | (2) | (3) | (4) | (5) |
| 1 | Internal Roads & Footpaths | Yes | 100% | |
| 2 | Water Supply | Yes | 100% | |
| 3 | Sewerage development | Yes | 100% | |
| 4 | Storms Water Drains | No | - | |
| 5 | Park Development | Yes | 100% | |
| 6 | Electricity Development | Yes | 100% | |
| 7 | Community Plots | No | - | |
| 8 | Treatment and disposal of sewage and Sullage water | No | - | |
| 9 | Solid Waste management & Disposal | No | - | |
| 10 | Water Conservation, Rain water harvesting | Yes | 100% | |
| 11 | Energy management | No | - | |
| 12 | Fire protection and fire safety requirements | No | - | |
| 13 | Electrical meter room, Sub-station, receiving station | No | - | |
| 14 | Block Boundary Development | Yes | 50% | |

After visiting the site, it has been observed that approx. 80% work has been completed

Yours Faithfully,

Ar Vikram Jangid CA / 2019/112029