FORM R-1

[seeRegulation 3(4)]

CERTIFICATE BY ARCHITECT

(To be uploaded by the Promoter on his webpage on the RERA website before withdrawal of money from separate account)

money from separate account)
To,
TheSAMANVAY BUILDMART PRIVATE LIMITED, FLAT NOT-01, 3RD, P NO. 189, MOTI NAGAR, QUEENS ROAD, VAISHALI NAGAR, Jaipur, Rajasthan, 302021. Subject: Certificate of percentage of completion of construction work of THE NEW DOOR of the Phase of the Project (RERA Registration Number is RAJ/P/2020/1276situatedKHASRA NO 153,160,161/2, CHATARPURA URF LALYA KABAS, Jaipur - 302026 (Rajasthan). on the demarcated by itsboundaries (latitude and longitude of the end points) to the North to the South to the East to the West village- KHASRA NO 153,160,161/2, CHATARPURA URF LALYA KABAS, Jaipur - 302026 (Rajasthan)District JAIPUR PIN 302023admeasuring7891.67 sq.mts. Area being developed by. SAMANVAY
BUILDMART PRIVATE LIMITED.
Sir,
IShri krishanhave undertaken assignment as Architect of certifyingpercentage of completion of construction work of theabove Building(s) of the Phase of the Project, situated on the KHASRA NO 153,160,161/2, CHATARPURA URF LALYA developed by SAMANVAY BUILDMART PRIVATE LIMITED.

1. Based on site inspection, with respect to each of the Building of the aforesaid RealEstateProject, I certify that as on the date, the percentage of work done foreach of the building of the Real Estate Project (registration number isRAJ/P/2020/1276underRajasthan RERA), is as per TABLE-A herein below. The percentage of the work executed with respect to each of the activity of the entire phase is detailed in TABLE-B.TABLE-A

Building Number A,B,C,D(to be prepared separately for each Building of the Project)

Time period 1stjan2023 to 31THmarch 2023C



T.	Tasks /Activity	Percentage of work	Block B	Block C	Block D
lo.		done(Approximately)			
		Block A			
1	Excavation	100%	100%	100%	100%
2	number of Basement(s) and Plinth	100%	100%	100%	100%
3	Stilt Floor	100%	100	100%	100%
4	number of Slabs of Super Structure	12	12	12	12
5	Internal Walls, Internal Plaster,	75%	95%	100%	100%
	Floorings within Flats/Premises,				
6	Doors and Windows to each of the	nil	65%	100%	100%
	Flat/ Premises.				
7	Sanitary Fittings within the	nil	30%	100%	100%
	Flat/Premises,				
	Electrical within the Flat/Premises				
	Fittings				
8	Staircases, Lifts Wells and Lobbies	12	12	12	12
	at each Floor levelconnecting				
	Staircases and Lifts, Overhead and				
	UndergroundWater Tanks.e. •				
9	The external plumbing and external	nil	60%	100%	100%
	plaster, elevation, completion of				
	terraces with waterproofing of the				
	Building/ Wing				
1	Installation of lifts, water pumps		30%	80%	80%
	Fire Fighting Fittings and Equipmen				
	as per CFO NOC, Electrical fitting				
	to Common Areas, electro				
	mechanical equipment, Complianc				
	to conditions of environment /CRA				
	NOC, Finishing to entrance lobby/s				
	plinth protection, paving of area	as			
	appurtenant to Building, Compoun	d			
	Wall and all other requirements a				
	may be required to obtain	in			
	Completion Certificate.				RIKRISH
			9		RCHITEC A/99/254:

TABLE-B
Internal and External Development Works in respect of the entire Registered Phase/Project.

Phase/Project.										
Sr.No	Common areas and Facilities/Amenities	Proposed (Yes/No)	Percentage of Work done	Block b	Block c	Block d				
(1)		(3)		NILL	80%	100%				
1	Internal Roads & Footpaths.		NILL NILL	NILL	80%	80%				
2	Water Supply		NILL 0%	0%	80%	80%				
3	Sewerage (chamber, lines,		NILL	NILL	NILL	NILL				
4	Storm Water Drains		30%	30%	30%	30%				
5	Landscaping& Tree Planting.		NILL	NILL	NILL	NILL				
6	Street Lighting		NILL	NILL	NILL	NILL				
7	Community Buildings		NILL	NILL	NILL	NILL				
8	Treatment and disposal of		NILL	NILL	NILL	NILL				
9	Solid Waste management &		NILL	60%	80%	90%				
10	Water conservation, Rain				NILL	NILL				
11	Energy management		NILL	NILL	70%	70%				
12	Fire protection and fire safety		35%	35%	NILL	NILL				
13	Electrical meter room, substation, receiving station.		NILL	NILL	NILL	MILL				
			100%	100%	100%	100%				
14	RAFT COPLITED OF		100%	100%	100%	100%				
15	COLUMN WITH		10070	10070	10070					
	TALLET I		90%	90%	90%	90%				
16	BOUNDARY WALL		100%	100%	100%	100%				
17	SITE		100%	100%	100%	100%				
18	EARTH BACK FILLING			100%	100%	100%				
19	LABOUR QUARTERS			100%	100%	100%				
20	STORE & GOWDON			100%	100%	100%				
21	SAMPLE FLAT		100/0	10070	100/0	100/0				



C-49, VIDYA APPARTMENT, BAPU NAGAR, JAIPUR

Place :JAIPUR. Date:31-3-2023

