Biswajit Sengupta. architect

b.arch.,fiia.,aiiid ph-09887488263/9672972807, 01493-515305 A 305, Block 2, RANGOLI, Ashiana Village Bhiwadi 301019, Alwar, Rajasthan email: bsen.architect@gmail.com

Date: 27.07.2022

FORM R-1

[see Regulation 3(4)]

CERTIFICATE BY ARCHITECT

(To be uploaded by the Promoter on his webpage on the RERA website before withdrawal of money from separate account)

To,
Ashiana Housing Limited
3rd Floor, Apex Mall
Lalkothi, Tonk Road
Jaipur-302015, Rajasthan.

Sub: Certificate of percentage of completion of construction work of 1 Building(s) of the Phase III of the Project Ashiana Daksh (RERA Registration Number RAJ/P/2020/1379) situated on the Plot bearing No./ Khasra Nos. 419 to 437 demarcated by boundaries (latitude and longitude of the end points of whole project 26.475126/75.514904 to the North-West 26.474973/75.514906 to the South-West 26.475.45/75.515244 to the North-East 26.474946/75.515201 to the South-East Village Srikishanpura Tehsil Sanganer District Jaipur PIN 302017 admeasuring 4240.78 sq.mts. Area being developed by Ashiana Housing Limited.

Sir,

- I, Biswajit Sengupta have undertaken assignment as Architect of certifying percentage of completion of construction work of the 1Building(s) of the Ashiana Daksh Phase III Block of the Project, situated on the plot bearing No./ Khasra Nos 419 to 437 Village Srikishanpura Tehsil Sanganer District Jaipur PIN 302017 admeasuring 4240.78 sq.mts. Area being developed by Ashiana Housing Limited.
- I, Biswajit Sengupta based on site inspection, with respect to each of the Building of the aforesaid Real Estate Project, I certify that as on the date 30-06-2022 the percentage of work done for each of the building of the Real Estate Project (registration number RAJ/P/2020/1379 under Rajasthan RERA), is as per TABLE-A herein below. The percentage of the work executed with respected to each of the activity of the entire phase is detailed in TABLE-B.

〈 BISWAJIT SENGUPTA ゔ B. Arch, FlIA, AllID Regd. Architect : CA/75/886

TABLE-A

Building Number B-01

(To be prepared separately for each Building of the Project)

Sr.No.	Tasks / Activity	Percentage of work done (Approximately) in Building No. B-01	
(1)	(2)	- Andrews	
1.	Excavation	100%	
2.	number of Basement(s) and Plinth	100%	
3.	Still Floor	100%	
4.	13 number of Stabs of Super Structure	100%	
5.	Internal Walls, Internal Plaster, Floorings within Flats / Premises, Doors and Windows to each of the Flat / Premises.	75%	
6.	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat / Premises.	25%	
7.	Staircases, Lifts Wells and Lobbies at each Floor level connecting staircases and Lifts, Overhead and Underground Water Tanks.	35%	
8.	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing.	50%	
9.	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, Compliance to conditions of environment / CRZ NOC, Finishing to entrance lobby/s, plinth protection, paying of areas appurtenant to Building, Compound Wall and all other requirements as may be required to obtain Completion Certificate.	10%	

BISWAJIT SENGUPTA
B. Arch, FIIA, AHD
Regd. Architect: CA/15/885

TABLE-B Internal and External Development Works in respect of the entire Registered Phase / Project.

Sr. No.	Common areas and Facilities / Amenities	Proposed (Yes/No)	Percentage of Work done	Details
(1)	(2)	(3)	(4)	(5)
]	Internal Roads & Footpaths			
2.	Water Supply	**************************************		
3.	Sewerage (Chamber, Lines, Septic Tank, STP).		70%	
4.	Storm Water Drains			
5.	Landscaping & Tree Plantings.	**************************************	****	
6.	Street Lighting			
7.	Community Buildings	**************************************	70%	
8.	Treatment and disposal of sewage and sullage water			
9.	Solid Waste management & Disposal.			
10.	Water conservation, Rain water harvesting			
11.	Energy management	بروسيون بازر بيسور وسرست متعدد		9
12.	Fire protection and fire safety requirements			
13.	Electrical meter room, sub-station, receiving station.		70%	
14.	Others (Option to Add more).		P # N #	

Yours Faithfully,

Signature & Mame' **BISWAJIT SENGUPTA**

A-305 BLOCK 2 RANGOLI

Ashiana Village Bhiwadi 301019

Alwar, Rajasthan

BISWAJIT SENGUPTA
B. Arch, FIIA, AIIID
Regd. Architect: CA/75/886

Place :Bhiwadi Date 27-07-2022