## FORM R-1

[seeRegulation 3(4)]

## CERTIFICATE BY ARCHITECT

(To be uploaded by the Promoter on his webpage on the RERA website before withdrawal of money from separate account)

_	_	
'	_	
- 1	$\alpha$	

10,
The SAMANVAY BUILDMART PRIVATE LIMITED, FLAT NOT-01, 3RD, P NO. 189, MOTI NAGAR, QUEENS ROAD, VAISHALI NAGAR, Jaipur, Rajasthan, 302021.  Subject: Certificate of percentage of completion of construction work of THE NEW DOOR of the Phase of the Project (RERA Registration Number is RAJ/P/2020/1276 situated KHASRA NO 153,160,161/2, CHATARPURA URF LALYA KABAS, Jaipur - 302026 (Rajasthan). on the demarcated by its boundaries (latitude and longitude of the end points) to the North to the South to the West village-KHASRA NO 153,160,161/2, CHATARPURA URF LALYA KABAS, Jaipur - 302026 (Rajasthan) District JAIPUR PIN 302023 admeasuring 7891.67 sq.mts. Area being developed by. SAMANVAY BUILDMART PRIVATE LIMITED .
Sir,
Shri krishan have undertaken assignment as Architect of certifyingpercentage of completion of construction work of the above Building(s) of the Phase of the Project, situated on the KHASRA NO 153,160,161/2, CHATARPURA URF LALYA KABAS, Jaipur - 302026 (Rajasthan). admeasuring 7891.67 sq.mts. Area being developed by SAMANVAY BUILDMART PRIVATE LIMITED.
1. Based on site inspection, with respect to each of the Building of the aforesaid
RealEstate Project, I certify that as on the date, the percentage of work done
foreach of the building of the Real Estate Project (registration number is
RAJ/P/2020/1276 under Rajasthan RERA), is as per TABLE-A herein below. The
percentage of the work executed with respect to each of the activity of the entire

Building Number A,B,C,D(to be prepared separately for each Building of the Project)

Time period 01<sup>st</sup> Oct 2020 to 31<sup>st</sup> Dec 2020

phase is detailed in TABLE-B.TABLE-A

SHRI KRISHAN CA/99/25451

Sr.	Tasks /Activity	Percentage of work	Block B	Block C	Block D
No.		done(Approximately)			
		Block A			
1	Excavation	nil	100%	100%	100%
2	number of Basement(s) and Plinth	nil	nil	nil	Nil
3	Stilt Floor	nil	nil	80%	80%
4	number of Slabs of Super Structure	nil	nil	4	4
5	Internal Walls, Internal Plaster,	nil	nil	18%	18%
	Floorings within Flats/Premises,				,
	Doors and Windows to each of the		H. L. L.		La make a
	Flat/ Premises.			短度でから4	THE BEST
6	Sanitary Fittings within the	nil	nil	10%	10%
	Flat/Premises,				
	Electrical within the Flat/Premises				
	Fittings	:1	nil	4	4
7	Staircases, Lifts Wells and Lobbies	nil		·	
	at each Floor level connecting				
	Staircases and Lifts, Overhead and				
	Underground Water Tanks.e. •  The external plumbing and external	nil	nil	nil	nil
8	plaster, elevation, completion of				
	terraces with waterproofing of the		ā		
	Building/ Wing		Tarris manufacture		1. 4. 4
9	Installation of lifts, water pumps,	nil	nil	nil	nil
	Fire Fighting Fittings and Equipment		EVILLE.		
	as per CFO NOC, Electrical fittings	新山山海岸沿		THE REAL PROPERTY.	
	to Common Areas, electro,	1			
	mechanical equipment, Compliance				
	to conditions of environment /CRZ				
	NOC, Finishing to entrance lobby/s,				
	plinth protection, paving of areas				
	appurtenant to Building, Compound	1		1 1 2 2	
	Wall and all other requirements as		4		
	may be required to obtain		(		
	Completion Certificate.	1 2 4			

PSHER MORRISSHAMM AAFORHITEECT COMMINION SAAS

TABLE-B

Internal and External Development Works in respect of the entire Registered Phase/Project.

Sr.No	Common areas and Facilities/Amenities	Proposed (Yes/No)	Percentage of Work done			
(1)		(3)	Block A	Block b	Block c	Block d
1	Internal Roads & Footpaths.		NILL	NILL	NILL	NILL
2	Water Supply		NILL	NILL	NILL	NILL
3	Sewerage (chamber, lines,		NILL	NILL	NILL	NILL
4	Storm Water Drains	THE PERSON	NILL	NILL	NILL	NILL
5	Landscaping& Tree Planting.		30%	30%	30%	30%
6	Street Lighting		NILL	NILL	NILL	NILL
7	Community Buildings		NILL	NILL	NILL	NILL
8	Treatment and disposal of		NILL	NILL	NILL	NILL
9	Solid Waste management &		NILL	NILL	NILL	NILL
10	Water conservation, Rain		NILL	NILL	NILL	NILL
11	Energy management		NILL	NILL	NILL	NILL
12	Fire protection and fire safety		NILL	NILL	NILL	NILL
13	Electrical meter room, substation, receiving station.		NILL	NILL	NILL	NILL
14	RAFT COPLITED OF		NILL	100%	100%	100%
15	COLUMN WITH		NILL	NILL	35%	35%
16	BOUNDARY WALL		90%	90%	90%	90%
17	SITE	<b>TLEANING</b>	100%	100%	100%	100%
18	EARTH BACK FILLING	i sizumeni	NILL	100%	100%	100%
19	LABOUR QUARTERS	Person		100%		100%
20	STORE & GOWDON			100%		100%
21	SAMPLE FLAT		100%	100%	100%	100%

YOUR RAISTING ARCHITECT CA/99/25451

Signature & Name SHRI KRISHAN

C-49, VIDYA APPARTMENT, BAPU NAGAR, JAIPUR

Place: JAIPUR. Date: 05-01-2021