Biswajit Sengupta. architect

b.arch.,fiia.,a d ph-09887488263/9672972807, 01493-515305 A 305, Block 2, RANGOLI, Ashiana Village Bhiwadi 301019, Alwar, Rajasthan email: bsen.architect@gmail.com

Date: 20.07.2021

FORM R-1

[see Regulation 3(4)]
CERTIFICATE BY ARCHITECT

To.

ASHIANA HOUSING LIMITED

Principal Place of Business:

Unit No. 4 & 5, 3rd Floor, Plot No.-2, Southern Park, Saket District Centre, Saket, New Delhi-110 017

Branch Office:

4th Floor Ashiana Village Centre Vasundhara Nagar Bhiwadi-301019

Subject: Certificate of percentage of completion of construction work of RESIDENTIAL COMPLEX Building(s) of the Project Ashiana Nirmay Phase 3 having RERA registration number RAJ/P/2019/1051 dated 22/07/2019, situated at Khasra No 169 (P), 171,172, 176, 174 & 179 Village Thara, Post Office Khijuriwas Alwar 301018, Raiasthan demarcated by its boundaries (latitude and longitude of the end points) 28 ° 09' 46.20" to the North, 28 ° 09' 46.27" to the South 76 ° 48' 49.11" to the East 76 ° 48 ' 49.76" to the West District Alwar Rajasthan, admeasuring 7146 sq.mts. Area being developed by ASHIANA HOUSING LIMITED

Sir,

- I, Biswajit Sengupta have undertaken assignment of certifying Estimated Cost for the Subject Real Estate Project proposed to the registered under RERA-Rajasthan, being G2 Building of Ashiana Nirmay Phase 3 situated on the plot bearing No Khasra No 159 (P), 171,172, 173, 174 & 179 Village Thara, Post Office Khijuriwas, Alwar 301018, Rajasthan admeasuring 7145 sq.mts. area being developed by ASHIANA HOUSING LIMITED.
- I, Based on site inspection, with respect to each of the Building of the aforesaid Real Estate Project, certify that as on the date 30°June 2021 the percentage of work done for each of the building of the Real Estate Project (registration number RAJ/P/2019/1051 under Rajasthan RERA), is as per TABLE-A herein below. The percentage of the work executed with respected to each of the activity of the entire phase is detailed in TABLE-B.

TABLE-A

Building Number ... B-05 (To be prepared separately for each Building of the Project)

Sr. No.	Tasks / Activity	Percentage of work done (Approximately)
(1)	(2)	(3)
1.	Excavation	100%
2.	O number of Basement(s) and 1 Plinth	100%
3.	Still Floor	100%
4.	13 number of Stabs of Super Structure	100%

5.	Internal Walls, Internal Plaster, Floorings within Flats / Premises, Doors and Windows to each of the Flat / Premises.	64%
6.	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat / Premises.	0%
7.	Staircases, Lifts Wells and Lobbies at each Floor level connecting staircases and Lifts, Overhead and Underground Water Tanks.	70%
8.	The external plumbing and externald plaster, elevation, completion of terraces with waterproofing of the Building/Wing.	59%
9.	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, Compliance to conditions of environment / CRZ NOC, Finishing to entrance lobby/s, plinth protection, paying of areas appurtenant to Building, Compound Wall and all other requirements as may be required to obtain Completion Certificate.	0%

TABLE-A
Building Number ..B-06 (To be prepared separately for each Building of the Project)

Sr. No.	Tasks / Activity	Percentage of work done (Approximately)	
(1)	(2)	(3)	
1.	Excavation	100%	
2.	O number of Basement(s) and 1 Plinth	100%	
3.	Still Floor	100%	
4.	13 number of Stabs of Super Structure	100%	
5.	Internal Walls, Internal Plaster, Floorings within Flats / Premises, Doors and Windows to each of the Flat / Premises.	63%	
6.	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat / Premises.	0%	
7.	Staircases, Lifts Wells and Lobbies at each Floor level connecting staircases and Lifts, Overhead and Underground Water Tanks.	70%	
8.	The external plumbing and externald plaster, elevation, completion of terraces with waterproofing of the Building/Wing.	61%	
9. Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, Compliance to conditions of environment / CRZ NOC, Finishing to entrance lobby/s, plinth protection, paying of areas appurtenant to Building, Compound Wall and all other requirements as may be rec, ired to obtain Completion Certificate.		0%	

Benegt Lugupta

(BISWAJIT SENGUPTA B. Arch, FIIA, AIIID Regd. Architect : CA/75/886

TABLE-BInternal and External Development Works in respect of the entire Registered Phase / Project.

Sr. No.	Common areas and Facilities / Amenities	Proposed (Yes/No)	Percentage of Work done	Details
[1]	(2)	(3)	(4)	(5)
1	Internal Roads & Footpaths		0%	e e
2.	Water Supply			UG TANK DONE WITH PHASE I
3.	Sewerage (Chamber, Lines, Septic Tank, STP).			STP OPRATIONAL
4.	Storm Water Drains		0%	
5.	Landscaping & Tree Plantings.		0%	
6.	Street Lighting		0%	
7.	Community Buildings		100%	CLUB HOUSE DONE WITH PHASE I
8.	Treatment and disposal of sewage and sullage water			STP OPRATIONAL
9.	Solid Waste management & Diaposal.		100%	SWM Operational
10.	Water conservation, Rain water harvesting		0%	
11.	Energy management		0%	
12.	Fire protection and fire safety requirements	ů.	0%	
13.	Electrical meter room, substation, receiving station.		100%	ESS Operational
14.	Others (Option to Add more).	. The state of the		

Yours Faithfully,

Signature & Name BISWAJIT SENGUPTA

A-305 BLOCK 2 RANGOLI Ashiana Village Bhiwadi 301019

Alwar , Rajasthan

Place :Bhiwadi Date : 20-07-2021 BISWAJIT SENGUPTA
B. Arch, FIIA, AlliD
Regd. Architect: CA/75/886