Biswajit Sengupta.

b.arch.,fiia.,aiiid ph-09887488263/9672972807, 01493-515305 A 305, Block 2, RANGOLI, Ashiana Village Bhiwadi 301019, Alwar, Rajasthan email: bsen.architect@gmail.com

Date:12.05.2021

FORM R-1

[see Regulation 3(4)]
CERTIFICATE BY ARCHITECT

(To be uploaded by the Promoter on his webpage on the RERA website before withdrawal of money from separate account)

To.

ASHIANA HOUSING LIMITED

Principal Place of Business:

Unit No. 4 & 5, 3rd Floor, Plot No.-2, Southern Park, Saket District Centre, Saket, New Delhi-110 017

Branch Office:

4th Floor Ashiana Village Centre Vasundhara Nagar Bhiwadi-301019

Subject: Certificate of percentage of completion of construction work of RESIDENTIAL COMPLEX Building(s) of the Project Ashiana Nirmay Phase 3 having RERA registration number RAJ/P/2019/1051 dated 22/07/2019, situated at Khasra No 169 (P), 171,172, 173, 174 & 179 Village Thara, Post Office Khijuriwas Alwar 301018, Rajasthan demarcated by its boundaries (latitude and longitude of the end points) 28 ° 09' 46.20" to the North, 28 ° 09' 46.27" to the South 76 ° 48' 49.11 " to the East 76 ° 48 ' 49.76 " to the West District Alwar Rajasthan, admeasuring 7146 sq.mts. Area being developed by ASHIANA HOUSING LIMITED

Sir.

- I, Biswajit Sengupta have undertaken assignment of certifying Estimated Cost for the Subject Real Estate Project proposed to the registered under RERA-Rajasthan, being O2 Building of Ashiana Nirmay Phase 3 situated on the plot bearing No Khasra No 169 (P), 171,172, 173, 174 & 179 Village Thara, Post Office Khiuriwas, Alwar 301018, Rajasthan admeasuring 7146 sq.mts. area being developed by ASHIANA HOUSING LIMITED.
- I, Based on site inspection, with respect to each of the Building of the aforesaid Real Estate Project, certify that as on the date 31* December 2020 the percentage of work done for each of the building of the Real Estate Project (registration number RAJ/P/2019/1051 under Rajasthan RERA), is as per TABLE-A herein below. The percentage of the work executed with respected to each of the activity of the entire phase is detailed in TABLE-B.

TABLE-ABuilding Number B-05 (To be prepared separately for each Building of the Project)

Sr. No.	Tasks / Activity	Percentage of work done (Approximately)	
(1)	. (2)	(3)	
1.	Excavation	100 %	
2.	O number of Basement(s) and 1 Plinth	100 %	
3.	Still Floor	100 %	
4.	13 number of Stabs of Super Structure	100 %	
5.	Internal Walls, Internal Plaster, Floorings within Flats / Premises, Doors and Windows to each of the Flat / Premises.	55 %	
6.	Sanitary Fittings within the Flat/Premises, Electrical Fittings	0%	

	within the Flat / Premises.	
7.	Staircases, Lifts Wells and Lobbies at each Floor level connecting staircases and Lifts, Overhead and Underground Water Tanks.	70 %
8.	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing.	46 %
9.	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, Compliance to conditions of environment / CRZ NOC, Finishing to entrance lobby/s, plinth protection, paying of areas appurtenant to Building, Compound Wall and all other requirements as may be required to obtain Completion Certificate.	0 %

TABLE-ABuilding Number B-06 (To be prepared separately for each Building of the Project)

Sr. No.	Tasks / Activity	Percentage of work done (Approximately)	
[1]	(2)	(3)	
1.	Excavation	100 %	
2.	O number of Basement(s) and 1 Plinth	100 %	
3.	Still Floor	100 %	
4.	13 number of Stabs of Super Structure	100 %	
5.	Internal Walls, Internal Plaster, Floorings within Flats / Premises, Doors and Windows to each of the Flat / Premises.	55 %	
6.	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat / Premises.	0%	
7.	Staircases, Lifts Wells and Lobbies at each Floor level connecting staircases and Lifts, Overhead and Underground Water Tanks.	70 %	
8.	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing.	46 %	
9.	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, Compliance to conditions of environment / CRZ NOC, Finishing to entrance lobby/s, plinth protection, paying of areas appurtenant to Building, Compound Wall and all other requirements as may be required to obtain Completion Certificate.	0%	

TABLE-B
Internal and External Development Works in respect of the entire Registered Phase / Project.

Sr. No.	Common areas and Facilities / Amenities	Proposed (Yes/No)	Percentage of Work done	Details
[1]	(2)	[3]	[4]	(5)
1	Internal Roads & Footpaths		0%	
2.	Water Supply			UG TANK DONE WITH PHASE I
3.	Sewerage (Chamber, Lines, Septic Tank, STP).			STP OPERATIONAL

4.	Storm Water Drains		0%	
5.	Landscaping & Tree Plantings.		0%	
6.	Street Lighting		0%	=
7.	Community Buildings		100%	CLUB HOUSE DONE WITH PHASE I
8.	Treatment and disposal of sewage and sullage water			STP OPERATIONAL
9.	Solid Waste management & Disposal.		100%	SWM Operational
10.	Water conservation, Rain water harvesting		0%	
11.	Energy management		0%	
12.	Fire protection and fire safety requirements		0%	
13.	Electrical meter room, substation, receiving station.	**	100%	ESS Operational
14.	Others (Option to Add more).	5		

Yours Faithfully,

Signature & Name

BISWAJIT SENGUPTA

A-305 BLOCK 2 RANGOLI

Ashiana Village Bhiwadi 301019

Alwar , Rajasthan

Place:Bhiwadi

Date: 12-05-2021

BISWAJIT SENGUPTA
B. Arch, FIIA, AIIID
Regd. Architect : CA/75/886