### FORM R-1

## [seeRegulation 3(4)]

# CERTIFICATE BY ARCHITECT

(To be uploaded by the Promoter on his webpage on the RERA website before

withdrawal of money from separate account)

To,

# The SAMANVAY BUILDMART PRIVATE LIMITED, FLAT NO.-T-01, 3RD, P NO. 189, MOTI NAGAR, QUEENS ROAD, VAISHALI NAGAR, Jaipur, Rajasthan, 302021.

Subject: Certificate of percentage of completion of construction work of THE NEW DOOR of the Phase of the Project (RERA Registration Number is RAJ/P/2020/1276 situated KHASRA NO 153,160,161/2, CHATARPURA URF LALYA KABAS, Jaipur - 302026 (Rajasthan). on the demarcated by its boundaries (latitude and longitude of the end points) \_\_\_\_\_\_\_\_ to the North \_\_\_\_\_\_\_\_ to the South \_\_\_\_\_\_\_\_ to the East \_\_\_\_\_\_\_\_ to the West \_\_\_\_\_\_\_\_ village-KHASRA NO 153,160,161/2, CHATARPURA URF LALYA KABAS, Jaipur -302026 (Rajasthan) District JAIPUR PIN 302023 admeasuring 7891.67 sq.mts. Area being developed by. SAMANVAY BUILDMART PRIVATE LIMITED .

Sir,

I Shri krishan have undertaken assignment as Architect of certifyingpercentage of completion of construction work of the above Building(s) of the Phase of the Project, situated on the KHASRA NO 153,160,161/2, CHATARPURA URF LALYA KABAS, Jaipur - 302026 (Rajasthan). admeasuring 7891.67 sq.mts. Area being developed by SAMANVAY BUILDMART PRIVATE LIMITED.

1. Based on site inspection, with respect to each of the Building of the aforesaid RealEstate Project, I certify that as on the date, the percentage of work done foreach of the building of the Real Estate Project (registration number is **RAJ/P/2020/1276** under Rajasthan RERA), is as per TABLE-A herein below. The percentage of the work executed with respect to each of the activity of the entire phase is detailed in TABLE-B.TABLE-A

Building Number A,B,C,D(to be prepared separately for each Building of the Project)

Time period 01<sup>st</sup> Jan 2022 to 31<sup>ST</sup> March 2022



Sr.	Tasks /Activity	Percentage of work	Block B	Block (	Block D
No.		done(Approximately)			
		Block A			00%
1	Excavation	100%	100%	100%	100%
2	number of Basement(s) and Plinth	100%	100%	100%	100%
3	Stilt Floor	100%	100	100%	12
4	number of Slabs of Super Structure	3	12	12	12
5	Internal Walls, Internal Plaster,	nil	80%	100%	10070
	Floorings within Flats/Premises,				25%
6	Doors and Windows to each of the	nil	nil	35%	2370
	Flat/ Premises.				80%
7	Sanitary Fittings within the	nil	20%	90%	80%
	Flat/Premises,				
	Electrical within the Flat/Premises				
	Fittings				
8	Staircases, Lifts Wells and Lobbies	3	12	12	12
	at each Floor level connecting				
	Staircases and Lifts, Overhead and				
	Underground Water Tanks.e. •				
9	The external plumbing and external	nil	nil	90%	90%
	plaster, elevation, completion of				
	terraces with waterproofing of the				
	Building/ Wing				
10	Installation of lifts, water pumps,	nil	nil	nil	nil
	Fire Fighting Fittings and Equipment				
	as per CFO NOC, Electrical fittings				
	to Common Areas, electro,				
	mechanical equipment, Compliance				
	to conditions of environment /CRZ				
	NOC. Finishing to entrance lobby/s.				
	plinth protection, paving of areas				
	appurtenant to Building. Compound				
	Wall and all other requirements as				
	may be required to obtain				
	Completion Certificate.				

S 

#### TABLE-B

Internal and External Development Works in respect of the entire Registered Phase/Project.

Sr.No	Common areas and Facilities/Amenities	Proposed (Yes/No)	Percentage of Work done	Df. I.b.	Block c	Block d
(1)		(3)	Block A	Block b	NILL	NILL
1	Internal Roads & Footpaths.	YES	NILL	NILL	NILL	NILL
2	Water Supply	YES	NILL	NILL	NILL	NILL
3	Sewerage (chamber, lines,	YES	NILL	NILL	NILL	NILL
4	Storm Water Drains	YES	NILL	NILL 30%	30%	30%
5	Landscaping& Tree Planting.	YES	30%	NILL	NILL	NILL
6	Street Lighting	YES	NILL	NILL	NILL	NILL
7	Community Buildings	YES	NILL	NILL	NILL	NILL
8	Treatment and disposal of	YES	NILL	NILL	NILL	NILL
9	Solid Waste management &	YES	NILL	NILL	NILL	NILL
10	Water conservation, Rain	YES	NILL			
11	Energy management	YES	NILL	NILL	NILL	NILL
12	Fire protection and fire safety	YES	NILL	NILL	NILL	NILL
13	Electrical meter room, sub- station, receiving station.	YES	NILL	NILL	NILL	NILL
	RAFT COPLITED OF		NILL	100%	100%	100%
			30%	100%	100%	100%
15	COLUMN WITH					
16	BOUNDARY WALL		90%	90%	90%	90%
	SITE		100%	100%	100%	100%
	EARTH BACK FILLING		100%	100%	100%	100%
	ABOUR QUARTERS		100%	100%	100%	100%
19 1	STORE & GOWDON		100%	100%	100%	100%
	SAMPLE FLAT		100%	100%	100%	100%

Yours Faithfully,

CA/99/25 Signature & Name SHRI KRISHAN

C-49, VIDYA APPARTMENT, BAPU NAGAR, JAIPUR

Place : JAIPU'R. Date: 25-04-2022