Biswajit Sengupta.

architect b.arch..fiia..aiiid

ph- 09887488263/9672972807. 01493-515305 A 305, Block 2, RANGOLI, Ashiana Village Bhiwadi 301019, Alwar, Rajasthan email: bsen.architect@gmail.com

Date :08.10.2022

FORM R-1

[see Regulation 3(4)] CERTIFICATE BY ARCHITECT

To.

ASHIANA HOUSING LIMITED

Principal Place of Business:

Unit No. 4 & 5, 3" Floor, Plot No.-2, Southern Park, Saket District Centre, Saket, New Delhi-110 017

Branch Office:

4th Floor Ashiana Village Centre Vasundhara Nagar Bhiwadi-301019

Subject : Certificate of percentage of completion of construction work of RESIDENTIAL COMPLEX Building(s) of the Project Ashiana Nirmay Phase 4 having RERA registration number RAJ/P/2021/1554 dated 10/06/2021, situated at Khasra No 169 (P), 171,172, 173, 174 & 179 Village Thara, Post Office Khijuriwas Alwar 301018, Rajasthan demarcated by its boundaries (latitude and longitude of the end points) 28 ° 09' 46 .20" to the North, 28 ° 09' 46.27" to the South 76 ° 48' 49 .11 " to the East 76 ° 48 ' 49.76 " to the West District Alwar Rajasthan, admeasuring 10471 sq.mts. Area being developed by ASHIANA HOUSING LIMITED

Sir.

I, Biswajit Sengupta have undertaken assignment of certifying Estimated Cost for the Subject Real Estate Project proposed to the registered under RERA-Rajasthan, being O2 Building of Ashiana Nirmay Phase 4 situated on the plot bearing No Khasra No 169 (P), 171,172, 173, 174 & 179 Village Thara, Post Office Khijuriwas, Alwar 301018, Rajassthan admeasuring 7146 sa.mts. area being developed by ASHIANA HOUSING LIMITED.

I, based on site inspection, with respect to each of the Building of the aforesaid Real Estate Project, certify that as on the date 30th September 2022 the percentage of work done for each of the building of the Real Estate Project (registration number RAJ/P/2021/1554 dated 16/07/2021 under Rajasthan RERA), is as per TABLE-A herein below. The percentage of the work executed with respected to each of the activity of the entire phase is detailed in TABLE-B.

Sr. No.	Tasks / Activity		Percentage of work done (Approximately)		
[1]	(2)		(3)		
1.	Excavation	100%		-	
2.	O number of Basement(s) and 1 Plinth	100%			
З.	Still Floor	100%			
4.	11 number of Stabs of Super Structure	100%		· . · ·	
5.	Internal Walls, Internal Plaster, Floorings within Flats / Premises, Doors and Windows to each of the Flat / Premises.	40%		2	
6.	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat / Premises.	0%			
7.	Staircases, Lifts Wells and Lobbies at each Floor level connecting staircases and Lifts, Overhead and Underground Water Tanks.	0%			
8.	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the	18%			

TABLE-A

	Building/Wing.		
9.	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, Compliance to conditions of environment / CRZ NOC, Finishing to entrance lobby/s, plinth protection, paying of areas appurtenant to Building, Compound Wall and all other requirements as may be required to obtain Completion Certificate.	0%	2

TABLE-A

Building Number.B-07 (To be prepared separately for each Building of the Project)

Sr. No.	Tasks / Activity	Percentage of work done (Approximately)		
[1]	(2)	[3]		
1.	Excavation	100%		
2.	0 number of Basement(s) and 1 Plinth	100%		
З.	Still Floor	100%		
4.	11 number of Stabs of Super Structure	100%		
5.	Internal Walls, Internal Plaster, Floorings within Flats / Premises, Doors and Windows to each of the Flat / Premises.	43%		
6.	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat / Premises.	D%		
7.	Staircases, Lifts Wells and Lobbies at each Floor level connecting staircases and Lifts, Overhead and Underground Water Tanks.	D%		
8.	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing.	19%		
9.	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, Compliance to conditions of environment / CRZ NOC, finishing to entrance lobby/s, plinth protection, paying of areas appurtenant to Building, Compound Wall and all other requirements as may be required to obtain Completion Certificate.	0%		

Sr. No.	Common areas and Facilities / Amenities	Proposed Percentage of (Yes/No) Work done		Details
[1]	(2)	(3)	[4]	[5]
1	Internal Roads & Footpaths	n. ² .8	0%	
2.	Water Supply		۵%	UG TANK DONE WITH PHASE I
З,	Sewerage (Chamber, Lines, Septic Tank, STP).		0%	STP OPRATIONAL
4.	Storm Water Drains		D%	
5.	Landscaping & Tree Plantings.		0%	

TABLE-B

6.	Street Lighting		0%		
7.	Community Buildings	2.	100%	CLUB HOUSE DONE WITH PHASE I	
8.	Treatment and disposal of sewage and sullage water		-	STP OPRATIONAL	
9	Solid Waste management & Disposal.		100%		
10.	Water conservation, Rain water harvesting		0%		
11.	Energy management		0%		
12.	Fire protection and fire safety requirements	-	0%		
13.	Electrical meter room, sub- station, receiving station.		100%	ESS Operational	
14.	Others (Option to Add more).	-			

Yours Faithfully,

m An Signature & Name

BISWAJIT SENGUPTA A-305 BLOCK 2 RANGOLI Ashiana Village Bhiwadi 301019 Alwar, Rajasthan

BISWAJIT SENGUPTA B. Arch, FIIA, AIIID Regd. Architect : CA/75/886

Place: Bhiwadi Date: 8ª Oct 2022